

3-9-90  
12.3.8 v.5

# ASH GROVE CEMENT WEST, INC.

SEATTLE, WA 98134

Inter-Office Memorandum

March 9, 1990

Date \_\_\_\_\_

To Steve Sheridan *VP. EX ✓*

From Ken Rone

Copies to DOUG KOLB

Subject PCB Transformers

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

Transformer	Status	PCB Content	Volume
TC1	STORAGE	24 PPM	31 GAL
TC2	STORAGE	22 PPM	31 GAL
TC3	STORAGE	18 PPM	31 GAL
TC4	STORAGE	13 PPM	100 GAL
TC5	STORAGE	8 PPM	100 GAL
TC6	STORAGE	8 PPM	100 GAL
TC7	STORAGE	8 PPM	19 GAL
TC8	STORAGE	5 PPM	19 GAL
TC9	STORAGE	5 PPM	19 GAL
TC14	STORAGE	6 PPM	150 GAL
TC15	STORAGE	5 PPM	150 GAL
TC16	STORAGE	5 PPM	150 GAL
TC17	STORAGE	* PPM	9 GAL
TC18	STORAGE	* PPM	9 GAL
TC19	STORAGE	* PPM	9 GAL
TC28	STORAGE	11 PPM	154 GAL
TC29	STORAGE	10 PPM	154 GAL
TC30	STORAGE	9 PPM	154 GAL
TC31	STORAGE	12 PPM	20 GAL
TC32	STORAGE	12 PPM	20 GAL
TC33	STORAGE	13 PPM	20 GAL

TOTAL 21 UNITS (plus 16 oil switches which have not been tested)

\* These were drained of fluid containing less than 50 ppm and refilled with non PCB oil. They have not been retested since.

Note: The Seattle East Terminal does not report these as being stored or generated. It has come to my attention that accumulations of such dangerous wastes must be reported if stored over 90 days in volumes of 2200 lbs or greater (180 days for 220 to 2200 lbs.). Your advice on what action to take would be appreciated.

*AM*

USEPA SF



1261555

AGC2F000001